

ISO 4014 / DIN 931



| | | | | |
|-------------|-----|-----|----|-----|
| d | M4 | M5 | M6 | M 8 |
| s | 7 | 8 | 10 | 13 |
| k | 2,8 | 3,5 | 4 | 5,3 |
| b (L ≤ 125) | 14 | 16 | 18 | 22 |
| b (L > 125) | - | 22 | 24 | 28 |

| | | | | | |
|-------------|-----------|-----------|-----------|------|-------|
| d | M10 | M12 | (M14) | M 16 | (M18) |
| s | 17 ISO 16 | 19 ISO 18 | 22 ISO 21 | 24 | 27 |
| k | 6,4 | 7,5 | 8,8 | 10 | 11,5 |
| b (L ≤ 125) | 26 | 30 | 34 | 38 | 42 |
| b (L > 125) | 32 | 36 | 40 | 44 | 48 |
| b (L > 200) | 45 | 49 | 53 | 57 | 61 |

| | | | | | | | |
|-------------|------|-----------|-----|-------|------|-------|------|
| d | M20 | (M22) | M24 | (M27) | M30 | (M33) | M36 |
| s | 30 | 32 ISO 34 | 36 | 41 | 46 | 50 | 55 |
| k | 12,5 | 14 | 15 | 17 | 18,7 | 21 | 22,5 |
| b (L ≤ 125) | 46 | 50 | 54 | 60 | 66 | 72 | 78 |
| b (L > 125) | 52 | 56 | 60 | 66 | 72 | 78 | 84 |
| b (L > 200) | 65 | 69 | 73 | 79 | 85 | 91 | 97 |