

# ISO 4014 / DIN 931



d	M4	M5	M6	M 8
s	7	8	10	13
k	2,8	3,5	4	5,3
b (L ≤ 125)	14	16	18	22
b (L > 125)	-	22	24	28

d	M10	M12	(M14)	M16	(M18)
s	17 ISO 16	19 ISO 18	22 ISO 21	24	27
k	6,4	7,5	8,8	10	11,5
b (L ≤ 125)	26	30	34	38	42
b (L > 125)	32	36	40	44	48
b (L > 200)	45	49	53	57	61

d	M20	(M22)	M24	(M27)	M30	(M33)	M36
s	30	32 ISO 34	36	41	46	50	55
k	12,5	14	15	17	18,7	21	22,5
b (L ≤ 125)	46	50	54	60	66	72	78
b (L > 125)	52	56	60	66	72	78	84
b (L > 200)	65	69	73	79	85	91	97